

AUSPLOW FARMING SYSTEMS

6 Davison Road, Jandakot 6164 PO Box 5010, South Lake 6964 Western Australia
Ph: (61 8) 9417 8877 Fax: (61 8) 9417 8878
e-mail: ausplow@ausplow.com.au

PARTS BULLETIN No. 9-15

29-04-15

**Subject: PART NO LONGER AVAILABLE – ROCKER ASSEMBLY P/N 01477
NEW PART – CAST ROCKER ASSEMBLY P/N 27067**

From March 2015 all new machines are now supplied with cast rocker assemblies.

Effective immediately steel rocker assembly Part Number 01477 has been superseded and replaced with the new cast rocker assembly P/N 27067.

For customers replacing their steel rocker assembly P/N 01477, longer pins will be required for attaching the turnbuckle, pivot and cylinder pins remain unchanged.



27067 Rocker Assembly Cast
05124 Pin 20x180mm

Replacement turnbuckle pins for steel rocker assemblies will continue to be supported;

05125 Pin 30x136mm

Carl Myers
Parts Manager

AUSEEDER DBS - MULTISTREAM - EASITILL
www.ausplow.com.au

Ausplow Farming Systems P/L as trustee for Ausplow Farming Systems Trust ABN 57 168 859 933 Trading as Ausplow Farming Systems