AUSPLOW FARMING SYSTEMS

6 Davison Road, Jandakot 6164 PO Box 5010, South Lake 6964 Western Australia Ph: (61 8) 9417 8877 Fax: (61 8) 9417 8878 e-mail: ausplow@ausplow.com.au

PARTS BULLETIN No. 1-09

16-02-09

Subject: AUSEEDER BLADE REPLACEMENTS -

END OF PROGRAMME.

Our Bulletin No. 2-08 detailed a temporary extension to the Ausplow Warranty Policy in response to an unprecedented level of problems with Tungsten Tipped Blades.

In that bulletin, a target date of 30th June 2008 was set for the return of blades to Dealer's premises for consideration under this programme. It was felt that any machine owner who had genuinely experienced problems would seek early resolution and would be happy to receive new replacements for those blades with obvious problems.

Generally, the response was as expected and we appreciated the cooperation of the large majority. Perhaps inevitably, there were some apparent attempts to benefit unreasonably from our programme. There has also been a continuing flow of blade returns well after the target closing date.

While Ausplow has been very lenient in this regard, and have extended the benefit of the doubt further than might be justified, this must come to a conclusion.

This programme has now ended and no further claims will be considered. The normal provisions of the Ausplow Warranty Policy, which excludes all ground engaging wear-parts, will apply.

Mike Kilroy

Parts Manager