# **AUSPLOW FARMING SYSTEMS**

6 Davison Road, Cockburn 6164 PO Box 5010, South Lake 6964 Western Australia Ph: (61 8) 9417 8877 Fax: (61 8) 9417 8878 e-mail: ausplow@ausplow.com.au

# PARTS BULLETIN No. 3-17

21-07-17

**Subject:** MODIFICATION TO MULTISTREAM TANK INSERT PLATE

MODIFICATION TO MULTISTREAM METERING UNIT CHASSIS MODIFICATION TO MULTISTREAM LIQUID SUMP PLATE

#### Modification to Multistream Tank Insert Plate

All Multistream tanks are now manufactured with a new captive 10mm nut on the tank insert plate, instead of the previous 12mm nut.

This change occurred in December 2016 and affects all model Multistream tanks.

Customers purchasing replacement tanks for Multistream's bins built pre-December 2016, will need to purchase replacement setscrews and washers to suit;

09810 Washer Flat M10 Large SS x12

09811 Screw M10x20 Socket Head Cap SS304 x12


## Modification to Multistream Metering Unit Chassis

All Multistream metering unit chassis are now manufactured with smaller 13.5mm mounting holes, instead of the previous 15.5mm mounting holes.

Customers purchasing a replacement metering unit for machines built pre-December 2016 will require drilling the metering unit chassis mounting holes from 13.5mm to 15.5mm. This will provide additional clearance for any variations in the tank insert plate, and will assist in the installation process.

### Modification to Multistream Liquid Sump Plate

Similar to the metering unit chassis, liquid sump plates will also be manufactured with smaller 13.5mm mounting holes, instead of the previous 15.5mm mounting holes.



Carl Myers
Parts Manager

AUSEEDER DBS - MULTISTREAM - EASITILL www.ausplow.com.au