

AUSPLOW FARMING SYSTEMS

6 Davison Road, Jandakot 6164 PO Box 5010, South Lake 6964 Western Australia
Ph: (61 8) 9417 8877 Fax: (61 8) 9417 8878
e-mail: ausplow@ausplow.com.au


PARTS BULLETIN No. 3-15

04-03-15

Subject: PART SUPERSEDED -SEED TUBE ASSEMBLY WITHOUT BUSHES V2 P/N 01366
-RIB ASSEMBLY WITHOUT BUSHES V3 P/N 11350

Seed tube assembly without bushes Version2 part number 01366 has been Superseded by seed tube assembly Version2 with bushes P/N 01493.

Rib assembly without bushes (suits Version3) part number 11350 has been Superseded by rib assembly with bushes-2007 on P/N 11926.



01493 Seed Tube Assembly Version2
-With Bushes

11926 Rib Assembly with Bushes
-2007 On

Customers can continue purchasing replacement bushes P/N 01133, but assemblies without bushes P/N 01366 and P/N 11350 will no longer be available for sale.

Carl Myers
Parts Manager

AUSEEDER DBS - MULTISTREAM - EASITILL
www.ausplow.com.au

Ausplow Farming Systems P/L as trustee for Ausplow Farming Systems Trust ABN 57 168 859 933 Trading as Ausplow Farming Systems